


# FMF


Fast Multi Frequency



- 45 kHz
- 35 kHz
- 28 kHz
- 21 kHz
- 15 kHz
- 7 kHz
- 4 kHz



Choose the Fast and simultaneous Multi Frequency programs or between 49 single frequencies from 4 to 45 kHz.



The above graphic illustrates the sensitivity and the iron discrimination capability depending on frequency and the advantage of Fast Multi Frequency programs covering a large spectrum of targets. This is only a basic schematic which can vary depending the programs and real terrain conditions.

